



## HBC RADIOMATIC Stock List

Part No : HBC- FSE 510  
Part No : (580-00-00063)  
Part No : 001-01-00235  
Part No : 003-05-00030  
Part No : 004-02-00018  
Part No : 005-01-00554  
Part No : 011-01-00086  
Part No : 011-01-00171  
Part No : 011-01-00235  
Part No : 011-01-00400  
Part No : 050-01-00046  
Part No : 050-01-00069  
Part No : 099-01-00039  
Part No : 099-01-00123 / Z-M00021  
Part No : 099-01-00163  
Part No : 099-01-00165  
Part No : 099-01-00165 / Z-Z00005  
Part No : 099-01-00166 / Z-Z00006  
Part No : 099-01-00167  
Part No : 099-01-00251 / A-S00020  
Part No : 099-01-00299  
Part No : 099-01-00619  
Part No : 099-01-00636  
Part No : 099-01-00653  
Part No : 099-01-00736  
Part No : 099-01-00759

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: [info@adamsint.net](mailto:info@adamsint.net) Web: <http://www.adamsllc.net/>

Get quote now ! [info@adamsint.net](mailto:info@adamsint.net)

Part No : 099-01-00759 / Z-G00099  
Part No : 099-01-00777  
Part No : 099-01-00795  
Part No : 100-0-727S1\_4S12  
Part No : 100-0-736M5\_GC11  
Part No : 10006240  
Part No : 100512C211004011DE0 FUNKSTEUERSYSTEM 512 CUBIX TX/TC64\_  
240V AC HBC (100) FSE PLASTIC  
Part No : 100512Q141004011DE0  
Part No : 100516M5I700L411DE0  
Part No : 101-90-00072  
Part No : 106-90-00055  
Part No : 107-90-00006  
Part No : 107-90-00020  
Part No : 190-01-00059  
Part No : 190-01-00059 US  
Part No : 190-01-00060  
Part No : 190-01-00067  
Part No : 1ec8f5e16735  
Part No : 221-01-00002  
Part No : 221-01-00005  
Part No : 225030  
Part No : 25TN CXT60620300P64ELMAS  
Part No : 300-HO-01  
Part No : 311507  
Part No : 3397-C-025  
Part No : 468479559  
Part No : 516-1126946  
Part No : 516-1600035/01  
Part No : 516-16010051  
Part No : 524-1206359/01  
Part No : 524-1206360/01  
Part No : 524-14 05801/01  
Part No : 527-00-00004 FST 736 SP.2 HAN  
Part No : 527-00-00017  
Part No : 531-18-00001 / FST 726 SP.3 HAN / TX/C64\_ FSE 10-30 V DC

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States  
Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: info@adamsint.net Web:  
<http://www.adamsllc.net/>

Get quote now ! info@adamsint.net

Part No : 580-00-00033  
Part No : 581-00-00041  
Part No : 5TN CXT50210050P55FFMBS"  
Part No : 6V/2100 Mah  
Part No : 7.2V/1.0Ah,Ni-MHFUB 06  
Part No : 726-17 0077  
Part No : 735-0700083 - V=6VDC - FREQ=433.1000-434.7500MHZ  
Part No : 735-0716615  
Part No : 736-111078  
Part No : 736-1110788  
Part No : 736-1110788-  
Part No : 736-1201095/1  
Part No : 736-21 01183  
Part No : 770-0800608  
Part No : 9325  
Part No : 99-01-00759  
Part No : AA020002  
Part No : AA020003  
Part No : AA020014  
Part No : AA050006  
Part No : AET00050 AET00380  
Part No : AET00080  
Part No : AET00330  
Part No : AET00380  
Part No : AET00380 US  
Part No : AJST0277  
Part No : AJST0278  
Part No : AJST0313  
Part No : AJT0278  
Part No : AS000800  
Part No : AS005600  
Part No : AS006000  
Part No : AS006600  
Part No : BA203030  
Part No : BA205031

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: info@adamsint.net Web: <http://www.adamsllc.net/>

Get quote now ! info@adamsint.net

Part No : BA209001  
Part No : BA209001 6V 800MAH  
Part No : BA209001(6V " 1800MAH) NIMH -AKKU FUB 9NM SCHWARZ  
Part No : BA209061  
Part No : BA209061 ( NiMH-Akku FuB 9 NM 6 V/800 mAh Farbe: blau )  
Part No : BA209061 , type FuB 9 NM  
Part No : BA209061.  
Part No : BA209062  
Part No : BA20906\_  
Part No : BA2090\_1 // (FuB 9NM) obsolete replaced by BA209061  
Part No : BA213020  
Part No : BA213030  
Part No : BA213031  
Part No : BA21303\_  
Part No : BA214061  
Part No : BA214061 battery for FLG110B obsolete, replaced by BA213020  
Part No : BA214061 obsolete replaced by BA213020  
Part No : BA2140P2  
Part No : BA222060  
Part No : BA223000  
Part No : BA223030  
Part No : BA223030.  
Part No : BA223031  
Part No : BA22303\_  
Part No : BA225000  
Part No : BA225001  
Part No : BA225030  
Part No : BA225030 (2100 mAh)  
Part No : BA225030 1500MAH,6V,NI-MH, replaced by BA225030 (2100 mAh)  
Part No : BA225030. replaced by BA225030.  
Part No : BA225030..  
Part No : BA2250308 obsolete replaced by BA225030  
Part No : BA225031  
Part No : BA22503\_  
Part No : BA225230 obsolete, replaced by BA225030

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: info@adamsint.net Web: <http://www.adamsllc.net/>

Get quote now ! info@adamsint.net

Part No : BATTERY FOR 512 HBC RADIOMATIC  
Part No : BE206000  
Part No : BV22799  
Part No : CM73014  
Part No : CM737012, replaced by CM737014  
Part No : CM737014  
Part No : CM737014.  
Part No : CM73707  
Part No : CM737070  
Part No : CM73707\_  
Part No : CUBIX  
Part No : CUBIX BLUE EDITION 6 X 2 STEP REMOTE  
Part No : FLG 110B  
Part No : FLG110D obsolete, replacement QA115600 + AJST0277 or QD115300  
Part No : FSE 308  
Part No : FSE 312  
Part No : FSE 508  
Part No : FSE 510  
Part No : FSE 516  
Part No : FSE 517  
Part No : FSE 524ECO  
Part No : FSE 726  
Part No : FSE 726-1111250  
Part No : FSE 727  
Part No : FSE 736  
Part No : FSE512 512-1205680  
Part No : FSE726 PB TC691-0E-A4-BK  
Part No : FSE736 00 TC691-0E-A3-OR  
Part No : FSS 726-1111249 - OBSOLETE, REPLACED BY 531-18-00001  
Part No : FSS Transmitter SPECTRUM 2  
Part No : FSS516 M500 TC241-0E-A3-OR  
Part No : FSS524 E200 TX641-0E-A3-OR  
Part No : FSS736S100TX691  
Part No : FST 511 quadrix ME  
Part No : FST 512 keynote ME

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: info@adamsint.net Web: <http://www.adamsllc.net/>

Get quote now ! info@adamsint.net

Part No : FST 512 micron 5 ME  
Part No : FST 512 quadrix ME  
Part No : FST 524 spectrum 1  
Part No : FST 736 SPECTRUM 2  
Part No : FST726 SA00 TC691-0E-A4A5  
Part No : FST727 L600 TC792-0E-D1D5-OROR  
Part No : FST736+SPECTRUM1  
Part No : FUB 05AAA  
Part No : FUB 06 Eex  
Part No : FUB10AA obosolete replacement BA213020  
Part No : FUB9NM - obsolete , replaced by BA209061 , type FuB 9 NM  
Part No : FuB 05AA  
Part No : FuB 06 Ex  
Part No : HBC RADIOMATIC - 516-0712386  
Part No : HBC RADIOMATIC - AA030003  
Part No : HBC RADIOMATIC - AA080011  
Part No : HBC RADIOMATIC - AS003400  
Part No : HBC RADIOMATIC - AS007500  
Part No : HBC RADIOMATIC - BA222060  
Part No : HBC RADIOMATIC - FSE 726 TYPICAL  
Part No : HBC-ADCON  
Part No : HBCO-FSE 516 RT1  
Part No : HBCO-FSS MICRON 5 RT1  
Part No : HBCÃ—FSSMicron5rt2  
Part No : HR145010  
Part No : HR145013  
Part No : HR145073  
Part No : HR145083  
Part No : HTO10130  
Part No : HTO10230  
Part No : HTO10330  
Part No : HTS10130  
Part No : HTS1B130  
Part No : HTS1B430  
Part No : IE120010

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: info@adamsint.net Web: <http://www.adamsllc.net/>

Get quote now ! info@adamsint.net

Part No : IE220001  
Part No : IE230001  
Part No : IE230005  
Part No : IE230005 obsolete replaced by UIE00003  
Part No : IE230015  
Part No : IE230016  
Part No : IE230017  
Part No : IE230018  
Part No : IE320002  
Part No : IE320003  
Part No : IE320004  
Part No : IE320005  
Part No : IO011011010023  
Part No : JP200070  
Part No : JP220070  
Part No : JPPPZ073  
Part No : JPPPZ07\_  
Part No : KMS100FA  
Part No : KMS100FA-US  
Part No : KSE10001  
Part No : KSE10001 US  
Part No : KST10001 US  
Part No : MC03-E006-001  
Part No : MR-IE230019 can not be offered separately,only as Set UIE00002  
Part No : MR508033  
Part No : MR509043  
Part No : MR726010 110284  
Part No : MS-1051-3600MC  
Part No : MT11-89001435-PA  
Part No : MTE11061  
Part No : MTM4102  
Part No : MTS23012 obsolete,replaced by MTS23015  
Part No : MTS23015  
Part No : Micron5  
Part No : Model - eco

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: info@adamsint.net Web: <http://www.adamsllc.net/>

Get quote now ! info@adamsint.net

Part No : Model - spectrum 1

Part No : Model - spectrum 2

Part No : Model - technos

Part No : NC BATTERY FUB 05 AA, 6V 500MAH NR. 05 06 obsolete, replaced by BA225030

Part No : NC BATTERY FUB05AA, 6V 500MAH NR05 00 REPLACED BY BA225030

Part No : NICD BATTERY FUB 06 EEX

Part No : NIMH BA225030

Part No : NiMH-Akku FuB 06 Ex

Part No : NiMH-Akku FuB 9 NM (BA209061)

Part No : OE736011

Part No : OP737014 // 110509 obsolete replaced by OP737071

Part No : OP737071

Part No : OP73707\_

Part No : OR005120 KW45/07 A

Part No : OR005170 KW02/07 A

Part No : OS726010

Part No : QA108600

Part No : QA109600

Part No : QA115600

Part No : QA115600/QD115300

Part No : QD109300

Part No : QD115300

Part No : QE111400

Part No : QUANDRIX 512

Part No : RADIOMATIC ILOG

Part No : RE.0444 US 1CB 0.06 CA

Part No : S/N 512-1401071 MODEL QUADRÄ°X

Part No : SS:CO:0169

Part No : Stand for Battery for remote Type FST 722, obsolete, replaced by BA213020

Part No : TC 641/681

Part No : TC641036

Part No : TC643044

Part No : TC643046

Part No : TX 641/681, joystick

Part No : TX 641/681, remotecontrol

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: info@adamsint.net Web: <http://www.adamsllc.net/>

Get quote now ! info@adamsint.net



Part No : UIE00002

Part No : UIE00003

Part No : UIE00003 US

Part No : UIE00003.

Part No : UQA00001

Part No : charger for battery BA225030 replaced by 190-01-00059

Part No : patrol (Ser.Nr.808-0300251) obsolete, replaced by patrol D  
(130511PD11014171DE0)

Part No : patrol D (130511PD11014171DE0)

Part No : ■■■■225030