



## JOHNSON FLUITEN Stock List

Part No : r-rh031 r031023541 B3F1Q  
Part No : -rebuild kit  
Part No : 09-836S-7  
Part No : 1400795.243  
Part No : 1600016.243  
Part No : 1600596.243  
Part No : 3 19L 111Q0550001 / 531.0000  
Part No : 4200RXB2  
Part No : 4203  
Part No : 46-189-0426-KT  
Part No : 5P8C10  
Part No : 8064130EU3  
Part No : 91812.243  
Part No : BEW/S 404-B-2  
Part No : BEW/S 404-B-2 FINNED COOLER FAN 7.4-A  
Part No : CB3D035025062  
Part No : CFLA009028407  
Part No : EPDM FIP25S 09-836S-7  
Part No : F50049  
Part No : F50426  
Part No : FRES 32-110 / G1 MQ1  
Part No : G-50367-0000  
Part No : G/50049  
Part No : G/5007/0005 1401592.243  
Part No : G/5869/0000  
Part No : G50049

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: [info@adamsint.net](mailto:info@adamsint.net) Web: <http://www.adamsllc.net/>

Get quote now ! [info@adamsint.net](mailto:info@adamsint.net)

Part No : GA 003002505 (50258243)  
Part No : GA 003025913  
Part No : GA003002505  
Part No : GA003005565  
Part No : GA006035534  
Part No : GA006035534 1602041.243  
Part No : GA009000601  
Part No : GA009002510  
Part No : GA00958070001  
Part No : GA012002217  
Part No : GA012002431  
Part No : GA012003595  
Part No : GAI009013508  
Part No : GFL009028400  
Part No : GFL009028405 Rebuilt kit for GFL009028405  
Part No : GFL009028407  
Part No : GFLA00902805  
Part No : GFLA009028405  
Part No : GFLA009028406  
Part No : GFLA009028407  
Part No : GFLA009028409  
Part No : GFLA009033515  
Part No : GFPA009031188  
Part No : GFR0090300110  
Part No : GFR009030110  
Part No : GFR009047302  
Part No : GFR4009030110  
Part No : GFRA009029898  
Part No : GFRA009030120  
Part No : GFRA009030121  
Part No : GFRA009030668  
Part No : GFRA009047937  
Part No : GFS009 M3SWC433Z12U31G GFS009028410  
Part No : GHP009027985  
Part No : GHR009038611

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: [info@adamsint.net](mailto:info@adamsint.net) Web: <http://www.adamsllc.net/>

Get quote now ! [info@adamsint.net](mailto:info@adamsint.net)

Part No : GL009015721  
Part No : GL009028400  
Part No : GLA006008824  
Part No : GLA009019953  
Part No : GLA009028405  
Part No : GRA009016061  
Part No : GSA0090002523  
Part No : GXA009003637 70259.243  
Part No : GXA009012310  
Part No : GXA009017353  
Part No : GZA009015776  
Part No : GZA009015776 80794.243  
Part No : GZA009015776 80794243  
Part No : GZA009015777 52271.243  
Part No : INT.A70X2.5 DIN472  
Part No : J2556 AI  
Part No : J2558Q  
Part No : J2558Q  
Part No : JOHNSON FLUITEN - STEAM JOINT  
Part No : JOHNSON FLUITEN - STEAM JOINT GASKET 20592-3  
Part No : JOINTS 7000  
Part No : KR019005348  
Part No : KR019047018  
Part No : KR038004210  
Part No : KR050020944  
Part No : KR076 B3  
Part No : KR076022904  
Part No : KR076B3  
Part No : KR089025515  
Part No : KRH025005664  
Part No : KRH025017738  
Part No : KRH031015717  
Part No : KRH031020074  
Part No : KRH038007591  
Part No : KRH050011299

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: [info@adamsint.net](mailto:info@adamsint.net) Web: <http://www.adamsllc.net/>

Get quote now ! [info@adamsint.net](mailto:info@adamsint.net)

Part No : KRH050011299 736461  
Part No : KRH064021657  
Part No : L-LH 012 G1 / 2-A  
Part No : L-LH 012 G1/2-A  
Part No : NR019B3M1R  
Part No : QRRJ0001  
Part No : R KRH089014949  
Part No : R KRH08904443  
Part No : R-050020620  
Part No : R-R 4038  
Part No : R-RH 012  
Part No : R-RH012  
Part No : R-RH019  
Part No : R-RH025  
Part No : R/RH-B4-F3N  
Part No : R009002641  
Part No : R009A-1M1R  
Part No : R009A1M1R  
Part No : R012001963  
Part No : R012002296 B3F1R  
Part No : R012004960  
Part No : R012010773-C3F1R-1503280.243  
Part No : R019003061  
Part No : R01900323  
Part No : R01900323 REPLACED BY R019B3M1R3/4  
Part No : R019003234  
Part No : R019004475 B3F1R  
Part No : R019020624  
Part No : R019B3M1L  
Part No : R025005179  
Part No : R025005366 (4973/A1L1U)  
Part No : R025008933  
Part No : R025009768  
Part No : R025010909  
Part No : R025020546

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: [info@adamsint.net](mailto:info@adamsint.net) Web: <http://www.adamsllc.net/>

Get quote now ! [info@adamsint.net](mailto:info@adamsint.net)

Part No : R025022341  
Part No : R031020614  
Part No : R031023541  
Part No : R031023541; B3F1Q; 1800031.243  
Part No : R038008225  
Part No : R038020616  
Part No : R038020631  
Part No : R038020632  
Part No : R038020632 REPAIR KIT  
Part No : R038026914  
Part No : R038B3F1L  
Part No : R038B3F1R  
Part No : R050 C3M1L/S/CPL  
Part No : R050.B3C1L2  
Part No : R050.B3C1R2  
Part No : R050020608  
Part No : R050020619  
Part No : R050020620; B3F1J; 1704172.243  
Part No : R050021182  
Part No : R05002800  
Part No : R064019646  
Part No : R064019646 B3L1J 2000645.243  
Part No : R064030140; B3F1J; 1702287.243  
Part No : R064030187 B3L1X  
Part No : R076 - B3L1J  
Part No : R076019651  
Part No : R076021327  
Part No : R076022912  
Part No : R076022913  
Part No : R076026401  
Part No : R076B3L1J  
Part No : R076B3L1R  
Part No : R38003042  
Part No : RH009 B4M1R  
Part No : RH012B4F1R

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: [info@adamsint.net](mailto:info@adamsint.net) Web: <http://www.adamsllc.net/>

Get quote now ! [info@adamsint.net](mailto:info@adamsint.net)

Part No : RH019005373  
Part No : RH019016701  
Part No : RH025 B4M1R  
Part No : RH025004244  
Part No : RH025022340  
Part No : RH025022935  
Part No : RH025022935B4L1  
Part No : RH031 B4-F1-Q  
Part No : RH031010846  
Part No : RH038007158  
Part No : RH038009571  
Part No : RH038016301  
Part No : RH038017455  
Part No : RH038020678  
Part No : RH03872707.242-B4L1U  
Part No : RH050 T4L1R  
Part No : RH050020933  
Part No : RH050024576  
Part No : RH050024576 2 IN \*\*B4L1Z  
Part No : RH050T3L.1R  
Part No : RH064047468  
Part No : RH064047468 2-1/2  
Part No : RH076036853  
Part No : RH076B3M1R  
Part No : RID010X008AQ  
Part No : RL064028957  
Part No : RL064028957 5931 B3L1R 1301573 243  
Part No : RL064028957 5931 B3L1R 1900488.243  
Part No : RL102036662  
Part No : RO19003234  
Part No : RO19A3M1R  
Part No : Repair kits  
Part No : Rotary joint RH - 25 (two - way), with fixing flange- Rotary joint RH - 50 (two - way), with fixing flange  
Part No : S25510  
Part No : S2554 Q2

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: info@adamsint.net Web: <http://www.adamsllc.net/>

Get quote now ! info@adamsint.net

Part No : SX3504Q  
Part No : XR99005  
Part No : Z019008020  
Part No : Z050008104 A6L2Q  
Part No : gfra0009037345  
Part No : r-rh050  
Part No : rebuild kit

ADAMS INTERNATIONAL LLC USA 1275 Bloomfield Ave Unit 81 Fairfield 07004, New Jersey, the United States Phone : +1 (973) 228-4293 Fax: +1 (973) 858-0288 E-Mail: [info@adamsint.net](mailto:info@adamsint.net) Web: <http://www.adamsllc.net/>

Get quote now ! [info@adamsint.net](mailto:info@adamsint.net)